



b1	d2	L3	L	Lc
mm	mm	mm	mm	mm
7.85	3.96	9.5	25.1	26.2
9.40	5.08	11.9	31.3	33.1
12.57	5.94	14.3	38.6	40.6
12.57	5.94	14.3	42.0	43.8
15.75	7.92	19.1	50.3	53.3
15.75	7.92	19.1	53.5	55.0
18.90	9.53	23.8	61.8	66.1
18.90	9.53	23.8	65.0	68.3
25.22	11.10	28.6	79.6	83.6
31.75	14.27	38.1	103.0	107.8